WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

October 23, 2013

TO:	Internal File			
THRU:	Steve Christensen, Permit Supervisor 555.			
FROM:	Amanda Daniels, Hydrologist 🗚			
RE:	2013 First Quarter Water Monitoring, Castle Gate Holding Company, Castle Gate Mine, C/007/0004, WQ13-1, Task ID #4268			
Company (the The remainin former substa	astle Gate Mine is inactive and mostly reclaimed. The Castle Gate Holding e Permittee) received Phase III bond release for 57.44 acres on October 18, 2012. g acreage in the permit area consists of an adit known as Adit #1 (3 acres) and a tion in Hardscrabble Canyon (1.84-acres). This remaining 5.56 acres is covered by formance bond.			
Pertin 7.5-3, and tab	ent water monitoring requirement information is in the MRP in Sections 7.5-1 and le 7-16.			
1. Was data	submitted for all of the MRP required sites? YES NO			
Springs –	The Permittee is not required to monitor any springs at the Castle Gate Mine.			
Streams – The Permittee is required to sample four intermittent/ephemeral streams (B-11, B-12, B-28, B-45) for flow, and the laboratory parameters outlined in Table 7-16 each quarter.				
	ermittee monitored the intermittent/ephemeral streams on March 19, 2013. None of had any measurable flow.			
Wells–	The Permittee is not required to monitor any wells at the Castle Gate Mine.			
<u>UPDES</u> –	There are no active UPDES sites at the Castle Gate Mine			

Page 2 C/007/0004 WQ13-1 Task ID # 4268 October 24, 2013

	100 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1	****	October 24, 201.		
2.	Were all required parameters reported for each site?	YES	NO 🗌		
	Not applicable				
3.	Were any irregularities found in the data?	YES 🗌	NO 🗌		
	Not applicable				
4.	On what date does the MRP require a five-year re-sampling of baseline water data.				
The MRP does not require a five-year re-sampling of baseline water data.					
5. Based on your review, what further actions, if any, do you recommend?					
	None at this time.				

O:\007004.CG\WATER QUALITY\WG4268.DOCX